

# NAFLIC

*National Association For Leisure Industry Certification*

## Standards & Related Documents Sub-Committee

### TECHNICAL BULLETIN - OCTOBER 1993

#### 066. A.R.M. Quasar Service Bulletin

We have received a copy of Service Bulletin No. S.B. QSR 001 from the manufacturer A.R.M. (UK) Ltd of Unit 1, Enstone Airfield, Enstone, Oxford OX7 4NW (Tel.: 0608 677468 & Fax.: 0608 678765).

This points out that fatigue cracks have been found on the H frame upper pivots, radiating from the hinge pin holes, of a 10 year old Quasar.

The Bulletin asks Operators of Quasars to inspect for cracks in the areas identified in two diagrams. In the UK, of course, it will also be necessary for Appointed Persons to consider the problem.

The region of interest is inaccessible without some stripping down, and Appointed Persons will clearly need to decide upon the frequency of monitoring by NDT and otherwise.

We urge any person involved in the Thorough Examination of a Quasar to obtain a copy of the Service Bulletin direct from A.R.M.