

NAFLIC

National Association For Leisure Industry Certification

Standards & Related Documents Committee

TECHNICAL BULLETIN — AUGUST 2010

366. “Fairmatt” Type Miami Cracking

We have received notification of defects on a Miami Trip rides manufactured by Fairmatt Ltd, Eurofab Ltd, Nottingham (UK) Ltd & FGL. Cracks have been found at the junction of the spur wheel mounting plate and the main arm box-section as shown in figure 1.

Controllers are reminded that any weld repairs in safety related areas should be carried out by a suitably qualified welder and subsequently subjected to an appropriate NDT examination.



Figure 1.

The location of the cracking is indicated in the figure 2.

Committee Members:- Mr. D Dadswell(acting Chairman), Mr. Peter Smith,
Mr. John Green, Mr. Phil Mitchell, Mr. Daniel Cox, Mr. Mark Wolstenholme, Mr. David Geary, Mr. Graham Dockerty, Mr. John Shilling & Mr. David Inman
© August 2010

PO BOX 752, SUNDERLAND, SR3 1XX TEL & FAX: (0191) 523 9498




Figure 2. Corner cracking as indicated within the circles.

Committee Members:- Mr. D Dadswell(acting Chairman), Mr. Peter Smith,
Mr. John Green, Mr. Phil Mitchell, Mr. Daniel Cox, Mr. Mark Wolstenholme, Mr. David Geary, Mr. Graham Dockerty, Mr. John Shilling & Mr. David Inman
© August 2010

PO BOX 752, SUNDERLAND, SR3 1XX TEL & FAX: (0191) 523 9498

Committee Members:- Mr. D Dadswell(acting Chairman), Mr. Peter Smith,
Mr. John Green, Mr. Phil Mitchell, Mr. Daniel Cox, Mr. Mark Wolstenholme, Mr. David Geary, Mr. Graham Dockerty, Mr. John Shilling & Mr. David Inman
© August 2010

PO BOX 752, SUNDERLAND, SR3 1XX TEL & FAX: (0191) 523 9498