

433. PWS Sizzler Twist

We have received a report from a UK registered inspection body relating to cracking on the capstan shaft of a PWS Sizzler Twist. The committee understands that the cracking was found on all three shafts and that the ride was only a year old.

This is a well-known area that can fail on these devices and we would refer IBs to previous NAFLIC Technical Bulletins relating to these rides. IBs are reminded to look at these areas when carrying out inspections.



Committee Members: Mr. D Dadswell (Chairman), Mr. A Mellor (Secretary), Mr. P Smith, Mr. J Green, Mr. D Cox, Mr. M Thirkettle, Mr. I Davies, Mr. J Shilling & Mr. D Inman

www.naflic.co.uk

Supported By:

