

# NAFLIC

*National Association For Leisure Industry Certification*

## Standards & Related Documents Subcommittee

### TECHNICAL BULLETIN - JULY 1994

#### **092. Pinfari Looping Coaster Brake Blades**

NAFLIC members Leisure Technical Consultants Ltd have recently informed us of a problem relating to a Pinfari TL59 looping roller coaster.

The problem concerned a failed weld attaching the brake blade to the car chassis and resulted in the brake blade detaching from the car.

LTC have notified Pinfari of the failure and have requested the manufacturer to supply an appropriate Service Bulletin. They have also asked Pinfari to confirm whether the problem extends to cars which have brake blades / cars of the bolted-on type.

**PLEASE NOTE THIS REFLECTIVE CODE HS(G)81, NOW SUPERSEDED**

Committee Members :- Dr Garry Fawcett (Chairman), Mr Richard Barnes, Mr Bob Nicholls, Mr Les Howson,  
Mr Malcolm Tennant, Mr Peter Steffens

© NAFLIC July 1994

P.O. BOX NO. 9, BUXTON, DERBYSHIRE. SK17 9XF  
TEL: (0298) 77468 FAX: (0298) 70784