



NUMBER: B406R1139-0

DATE: SEPT. 3, 1993

SUPERSEDES:

SERVICE BULLETIN

Effective Serial Number: 40600193 THROUGH 40600693

Ride: CENTURY WHEEL

Subject: FENCE REWORK

Chance Rides, Inc. has become aware that on the CENTURY WHEEL it is possible for the side fences around the operator's pedestal to slide up and down in the connecting sockets if the operator leans against the back fence section. If the side fences were to come all of the way out of the connecting sockets, injury to the operator and/or damage to the fences could result.

Chance Rides, Inc. requires all owner's of the above noted CENTURY WHEEL amusement rides to perform the rework outlined in this bulletin. To properly perform this rework, order and install the following items, which are available at no charge if ordered within 90 days of the date on this bulletin.

<u>PART NUMBER</u>	<u>DESCRIPTION</u>	<u>QUANTITY</u>
25234000	Clevis Pin 1/4 x 7/8	2
65189900	R-Key 3/32	2

All work must be performed by qualified personnel, capable of understanding the function of the parts and their proper installation.

NOTICE

Use only those components authorized, specified or provided by Chance Rides, Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with any unauthorized alterations and/or modifications or additions and installations of unauthorized components.

Follow the rework instructions in this bulletin and return the Certification Of Compliance within 15 days from receipt of parts.

REWORK INSTRUCTIONS

1. Install fences around operator's platform, making sure fences are properly seated in connecting sockets.
2. Centered in socket area, drill a 1/4 inch diameter hole (two places, opposite sides of platform) through side of platform and one side of the fence tube.
3. Insert clevis pin from outside and secure in place with R-key from underneath platform.

