



NUMBER: B090R1169-A

DATE: APRIL 21, 1995

SUPERSEDES: B090R1169-0

SERVICE BULLETIN

Effective Serial Number: All Units - Chance Rides, Inc.
All Units - Chance Manufacturing Co., Inc.

Chance Rides, Inc. SPECIFICALLY DISCLAIMS ANY LIABILITY for losses associated with rides produced by Chance Manufacturing Company, Inc.

Ride: FALLING STAR, SKYDIVER, TRABANT Subject: Safe Rider Policy
WIPEOUT AND ZIPPER

This Chance Rides, Inc. Service Bulletin supersedes Service Bulletin number B090R1169-0. All copies of bulletin number B090R1169-0 should be destroyed.

Chance Rides, Inc. anticipates that it may be possible for a rider sitting in a seat on one of the above noted amusement rides to intentionally turn sideways in the seat, removing their legs from underneath the lap bar. If a rider does this, they are not properly secured and personal injury could result. In order to reduce the possibility of an unsafe condition from occurring, Chance Rides, Inc. highly recommends all owners/operators of the above noted amusement rides to adopt and enforce an operational policy that would inhibit such misuse of the ride.

One such policy which can be used to help inhibit the misuse of the amusement ride is a "no single rider" policy. Chance Rides, Inc., however, recognizes the fact that this type of policy may not be practical or suitable in all circumstances. It is therefore up to the individual owner/operator to develop their own operational policy which best meets their own needs while maintaining the safe operation of the ride.

All owner/operators must realize that horseplay or other behavior on the part of the rider, that leads to an unsafe condition must not be tolerated. All operators of amusement rides must follow the manufacturer's guidelines in giving their pre-operational instructions and warnings and then giving their undivided attention to the ride and its passengers at all times the ride is in motion. As stated in the operation/maintenance manuals, the operator must immediately stop the ride if anyone is in a dangerous or unsafe position on the ride.