

# CARES Notification

*This document contains technical information provided by a CARES member agency.  
This document is FOR INFORMATION ONLY.*

**Subject: Drive gear failure**

**Ride(s) affected: Fabbri Booster**

**Date: August 17, 2011**

**Source: Leisure Technical Consultants Limited (LTC; <http://www.ltci.co.uk/> )**

LTC has provided the following photograph of a drive gear (one of two) from a Fabbri Booster which failed during set-up. The photograph was supplied by a ride inspection body in the UK.

The manufacturer has been contacted, but as of this date has NOT issued a bulletin or official statement.

