



# WISDOM INDUSTRIES, Ltd.

## SERVICE BULLETIN

**DATE: FEBRUARY 23, 2009**

**RIDE: AVALANCHE**

**SUBJECT: HYDRAULIC DRIVE SYSTEM REPAIR**

**COMPLIANCE: IMMEDIATE AND AT TIME OF  
HYDRAULIC MOTOR REPAIR OR  
REPLACEMENT**

Following repair or replacement of Charlyn Hydraulic drive motor, check that the rotation speed of the ride is 21 RPM, in both directions.

If the speed of the ride is over 21 RPM, switch the two hoses on the repaired or replaced motor. Retime the ride.

If the speed of the ride is still over 21 RPM, contact Wisdom Industries, Ltd for instructions to adjust the speed of the ride.

➤ **SERIOUS INJURY CAN RESULT IF THE SPEED IS  
OVER 21 RPM**

Any questions, give Wisdom Industries, Ltd. a call.  
970-522-7515