

ZAMPERLA INC.
49 Fanny Road
Parsippany, New Jersey 07054-0598
USA
Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 98 LS1
Release Date: 3/20/98
Effective Date: 3/20/98
Supersedes: 97 LS3
Completion Date: As soon as possible
Page: 1 of 3

SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates: All
Ride Name: Lolli Swing	Affected Serial Nos.: All
Model Number: Lolli Swing	

Abstract Of Issue:

Cracks have been found in the welds located at the center column base plate junction and in the lower center frame structure.

Reason For Release:

This reinforcement kit when installed properly will strengthen the center column base plate junction and the lower center frame structure.

Action To Be Taken:

Examine the accompanying drawings and have a certified welder install the components of the column and frame reinforcement kit.

Detail Of Issue:

The reinforcement kit contains two drawings, one for the column base plate junction and one for the lower frame structure. The kit also contains the necessary metal components to complete this task.

Future Action To Be Taken:

None