

ZAMPERLA INC.
49 Fanny Road
Parsippany, New Jersey 07054-0598
USA
Phone: 973 334 8133 Fax: 973 334 6880

Bulletin No: 99 RS1
Release Date: 4/1/99
Effective Date: 4/1/99
Supersedes:
Completion Date: As soon as possible
Page: 1 of 4

SERVICE BULLETIN

Ride Manufacturer: Zamperla Inc.	Affected Production Dates:
Ride Name: Rotoshake	Affected Serial Nos.: RS42F153US95
Model Number: Rotoshake	




Abstract Of Issue:
Cracks have been found in the welds located at the connection of the fork arms to the central main arm.
See areas indicated on the accompanying diagram.

Reason For Release: Same.

Action To Be Taken: Magnetic particle testing by a certified NDT technician

Detail Of Issue:
If cracks have been detected in the above mentioned welds and confirmed, please contact Zamperla Inc.
for Notification of repair procedure.

Future Action To Be Taken:
Magnetic particle testing by a certified NDT technician annually.



CONTROLLO MT89005 REV.A 100%
 MAGNETIC PARTICLE TEST MT89005 REV.A 100%

