

Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. * PO Box 128
4536 State Route 7, New Waterford, Ohio 44445

Subject: Lap Bars ** Purpose of & Misuse of

ATTN: OWNER/OPERATOR

This bulletin pertains to the operation of your Majestic unit. This Service Bulletin must remain with the owner's manual at all times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. ** Fax 330/457-7490.

SERVICE BULLETIN

Date: July 17, 1992

S.B. Number: 92-8 Sheet 1 of 2

Notice:

This service bulletin is to inform our customers of problems we feel are attributed to the misuse of the lap bars. The purpose of the lap bar is for use as a safety restraint only.

#1 AREA OF CONCERN: The lap bars are not intended for use as a kickstand. When tipping the cars on their side, the result will put undue side stress on the bar. Due to the fact that the car weight may double because of excessive thrust.

#2 AREA OF CONCERN: Pulling the car forward, by hand, with the lap bar in an up position, will put undue stress on the bar.

#3 AREA OF CONCERN: Standing on the lap bar, in a down position, when servicing trolley wheels.

#4 AREA OF CONCERN: Lifting the cars off the floor with the lap bar.

RESULT FROM PULLING ON THE LAP BAR

This bulletin is to give our customers a better understanding of the lap bars intended purpose. Any lap bar failure must be sent to the factory for determination of proper warranty.

If you have any questions on factory standards or procedures on our equipment, contact Majestic Manufacturing, Inc. during normal business hours of 8:00 a.m. to 4:30 p.m. Monday through Friday, E.S.T. at 330/457-2447 or toll free at 1-888-MAJ-RIDE.

Majestic Manufacturing, Inc.

Majestic Manufacturing, Inc. * PO Box 128
4536 State Route 7, New Waterford, Ohio 44445

Subject: Lap Bars ** Purpose of & Misuse of

ATTN: OWNER/OPERATOR


This bulletin pertains to the operation of your Majestic unit. This Service Bulletin must remain with the owner's manual at all times. If you have any questions regarding the Bulletin, contact our office at 330/457-2447, M-F 8:00a.m. -4:30p.m. E.S.T. ** Fax 330/457-7490.

SERVICE BULLETIN


Date: July 17, 1992

S.B. Number: 92-8 Sheet 2 of 2

Notice:



Results from use as a Kickstand



Revised 01/06/03