



Bulletin No: 08 CB02
Release Date: 17/10/08
Effective Date: 17/10/08
Supersedes:
Completion Date: As soon as possible
Page: 1 of 1

NOTIFICATION

Ride Manufacturer: A. Zamperla S.p.A.	Affected Production Dates: All
Ride Name: Crazy Bus Family*	Affected Serial Nos.: All
Model Number: Crazy Bus Family	

Abstract Of Issue:

To verify the proper function of the drive motor brake.

Reason For Release:

To clarify required preventive maintenance.

Action To Be Taken:

- 1) Daily, stop an empty vehicle in either the 3 or 9 o'clock position to ensure brake is working properly. Some slippage before gondola comes to a complete stop is acceptable. Brake must be able to hold gondola in a stopped position outside of the home (station park) position.
- 2) Quarterly, visually inspect motor brake liner. If brake cannot hold gondola in a stopped position, then inspect immediately. Replace liner if necessary.

Detail of Issue:

Future Action To Be Taken:

*Crazy Bus Family = Crazy Bus, Crazy Sub, Fire Chief, etc.